

UST Service Provider List (Mountains)

Company			Listing Submitted	11/19/2018	Area of state conducts work	
ABC Global Contracting LLC 32032 28 Mile Road Lenox, Michigan 48048-			Phone (810) 533-2416 Fax Website abcglobalcontracting.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration: Yes		
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing: Yes		
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair: Yes		
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other: Yes		
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair: Yes		
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems: Yes		
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation: Yes		
Line Tightness Testing:	Yes			UST System Removal: Yes		
Environmental Service Firms				Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes			
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No			
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					

Company			Listing Submitted	8/4/2020	Area of state conducts work	
Advanced Environmental Services, Inc. PO Box 38218 Greensboro, NC 27438			Phone (336) 282-3586 Fax (336) 282-3587 Website advancedenvironmental.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No		
Line Tightness Testing:	No			UST System Removal: Yes		
Environmental Service Firms				Other:		
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No			
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No			
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes			
Oil and Solvent Recycling:	No	Other:				
Soil and Water Testing Lab:	No					

UST Service Provider List (Mountains)

Company		Listing Submitted		11/14/2018		Area of state conducts work	
Advanced Environmental Solutions, LLC P.O. Box 1426 Black Mountain, NC 28711		Phone (828) 664-9822 Fax (866) 425-2661 Website advancedenvironmentalsolutions.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	Yes			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		10/2/2017		Area of state conducts work	
AES of Greenville LLC 141 S. Market Street Washington, NC 27889		Phone (252) 758-3311 Fax (252) 481-5814 Website www.aes-nc.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	Yes			UST System Removal:			Yes
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	10/13/2017	Area of state conducts work	
Apex Engineering, PC 15850 Crabbs Branch Way Suite 200 Rockville, Maryland 20855-		Phone (301) 417-0200 Fax (301) 975-0169 Website www.apexc.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company				Listing Submitted	1/2/2018	Area of state conducts work	
Applied Science & Engineering, LLC 550 N. Reo Street Tampa, FL 33609		Phone (813) 207-5061 Fax (813) 288-1550 Website				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	7/30/2020	Area of state conducts work	
Blue Ridge Geological Services, Inc. 7356 Belmont Drive Trinity, NC 27370				Phone (336) 382-6849 Fax Website www.blueridgegeo.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes			UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes					UST System Removal:	No
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

Company				Listing Submitted	11/14/2018	Area of state conducts work	
Bunnell-Lammons Engineering Inc. 130 Oval Road Suite 200 Arden, NC 28704				Phone (828) 277-0100 Fax (828) 277-0110 Website www.blecorp.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	No
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:			Trust Fund Projects		
Soil and Water Testing Lab:	Yes						

UST Service Provider List (Mountains)

Company				Listing Submitted	11/14/2018	Area of state conducts work	
Cape Lookout Environmental Sciences, PLLC 8005 Clear Brook Drive Raleigh, NC 27615				Phone (919) 757-7901 Fax Website CapeLookoutEnv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	11/14/2018	Area of state conducts work	
Carbon Fuel Services, LLC 301 E Main Street Cherryville, NC 28021-				Phone (704) 419-9939 Fax Website www.carbonfuelservices.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:	Diesel Fuel Compliance Laboratory Testing	UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No	Diesel Fuel Polishing, Filtration, and Recovery Services			
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:	Diesel Fuel Additives and Tank Cleaning Agents				
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted		8/18/2020		Area of state conducts work	
Cathodic Protection Services, Inc. 445 Gap Creek Rd. Elizabethton, TN 37643				Phone (423) 895-1500 Fax (423) 542-8955 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No		
Line Tightness Testing:	No					UST System Removal:	No		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No						
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No						
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No						
Oil and Solvent Recycling:	No	Other:							
Soil and Water Testing Lab:	No								

Company				Listing Submitted		8/18/2020		Area of state conducts work	
Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305				Phone (910) 574-4748 Fax 253-681-05 Website www.ustcomonline.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Off	Overfill Prevention Equipment Operability Check:	Off			Dispenser Meter Repair/Calibration:	Off		
Containment Sump Testing:	Off	Statistical Inventory Reconciliation Services:	Off			Leak Detection Equipment Installation Servicing:	Off		
Corrosion Protection Design Experts:	Off	Spill Prevention Equipment Testing:	Off			Spill Bucket Installation Repair:	Off		
Corrosion Protection System Repairs:	Off	Tank Tightness Testing:	Off			UST Equipment Installation - Other:	Off		
Corrosion Protection System Testing:	Off	UST Internal Inspections (Integrity Assessments):	Off			UST Equipment Repair:	Off		
Leak Detection Equipment Operability Check:	Off	UST Internal Lining Inspections:	Off			UST System Installation - Complete Systems:	Off		
Leak Detection Monitoring Services:	Off	Other:				UST Piping/Sump Installation:	Off		
Line Tightness Testing:	Off					UST System Removal:	Off		
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:	Off	UST Compliance Consultants:	Yes						
Environmental Engineer/Geologist - Site Checks:	Off	UST Equipment Verification:	Off						
Environmental Engineer/Geologist Soil and GW Cleanu	Off	Waste Disposal and Treatment:	Off						
Oil and Solvent Recycling:	Off	Other:							
Soil and Water Testing Lab:	Off								

Company		Listing Submitted		8/18/2020		Area of state conducts work	
Charles Broadfoot & Associates, Inc. PO Box 53730 1827 Morganton Rd. Fayetteville, NC 28305		Phone (910) 574-4748 Fax 253-681-05 Website www.ustcomonline.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	Off	Overfill Prevention Equipment Operability Check:	Off	Dispenser Meter Repair/Calibration:		Off	
Containment Sump Testing:	Off	Statistical Inventory Reconciliation Services:	Off	Leak Detection Equipment Installation Servicing:		Off	
Corrosion Protection Design Experts:	Off	Spill Prevention Equipment Testing:	Off	Spill Bucket Installation Repair:		Off	
Corrosion Protection System Repairs:	Off	Tank Tightness Testing:	Off	UST Equipment Installation - Other:		Off	
Corrosion Protection System Testing:	Off	UST Internal Inspections (Integrity Assessments):	Off	UST Equipment Repair:		Off	
Leak Detection Equipment Operability Check:	Off	UST Internal Lining Inspections:	Off	UST System Installation - Complete Systems:		Off	
Leak Detection Monitoring Services:	Off	Other:		UST Piping/Sump Installation:		Off	
Line Tightness Testing:	Off			UST System Removal:		Off	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Off	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Off	UST Equipment Verification:	Off				
Environmental Engineer/Geologist Soil and GW Cleanu	Off	Waste Disposal and Treatment:	Off				
Oil and Solvent Recycling:	Off	Other:					
Soil and Water Testing Lab:	Off						

UST Service Provider List (Mountains)

Company		Listing Submitted		10/9/2017		Area of state conducts work	
Christopher Dunlap, P.G. 166 Michigan Avenue Asheville, NC 28806		Phone (828) 505-6301 Fax Website				Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		6/17/2020		Area of state conducts work	
Clark Group dba Clark Environmental Services, PC P.O. Box 10136 Wilmington, NC 28404		Phone (910) 392-5555 Fax (910) 392-5552 Website www.clarkgroup.us				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company			Listing Submitted	10/12/2017	Area of state conducts work
Cobb Environmental & Technical Services, Inc. P. O. Box 1602, Tupelo, MS 38802 871 South Green Street Tupelo, MS 38804			Phone (662) 841-0995 Fax (662) 841-0810 Website www.cobbenenv.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	Yes
Line Tightness Testing:	No			UST System Removal:	Yes
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company			Listing Submitted	11/14/2018	Area of state conducts work
Cohesion, Inc. 5216 Yates Mill Pond Road Raleigh, NC 27606			Phone (919) 233-8626 Fax (919) 233-8909 Website www.cohesion-inc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company			Listing Submitted	11/15/2018	Area of state conducts work
CROMPCO, LLC 1815 Gallagher Road Plymouth Meeting, PA 19462			Phone (800) 646-3161 Fax (610) 278-7621 Website www.crompco.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company			Listing Submitted	8/1/2019	Area of state conducts work
D.H. Griffin Wrecking, Inc. 4716 Hilltop Road Greensboro, NC 27407			Phone (336) 389-3647 Fax (336) 389-3647 Website www.dhgriffin.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	Yes
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes		
Oil and Solvent Recycling:	Yes	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company		Listing Submitted		6/20/2018		Area of state conducts work	
DAVENPORT 3722 Shipyard Boulevard Suite E Wilmington, NC 28412		Phone (910) 251-8912 Fax Website http://www.davenportworld.com/				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		11/15/2018		Area of state conducts work	
EMS Environmental, Inc. 117 South Hoover Road Durham, NC 27703		Phone (919) 596-0470 Fax (919) 596-0578 Website www.emsenv.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

UST Service Provider List (Mountains)

Company			Listing Submitted	10/18/2017	Area of state conducts work
Enviro Consulting 531 Pitts School Road NW Suite D Concord, NC 28027			Phone (704) 721-0101 Fax (704) 721-0102 Website www.envirocorp.net		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:	UST Lining Installation	UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company			Listing Submitted	8/4/2020	Area of state conducts work
Environmental Laboratories, Inc PO Box 1729 Travelers Rest, SC 29609			Phone (864) 370-0637 Fax (864) 752-0948 Website www.elabsinc.net		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	<u>Yes</u>
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	<u>Yes</u>
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	<u>Yes</u>	UST Equipment Repair:	<u>Yes</u>
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	<u>Yes</u>	UST System Installation - Complete Systems:	<u>Yes</u>
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:	<u>Yes</u>
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
Environmental Service Firms			Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company		Listing Submitted		11/15/2018		Area of state conducts work	
EnviroTrac Ltd. 7343 West Friendly Avenue Greensboro, NC 27410		Phone (336) 763-6025 Fax Website www.envirotrac.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company		Listing Submitted		7/30/2020		Area of state conducts work	
Envirovation Geologic Consulting and Mapping, PC 719-A Greenway Rd PO Box 3425 Boone, NC 28607		Phone	(828) 407-0613			Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
		Fax					
		Website	https://envirovationconsulting.com/				
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		11/16/2018		Area of state conducts work	
Evo Corporation 1703 Vargrave Street Winston-Salem, NC 27107		Phone	(336) 725-5844		Coastal (East of I-95):		Yes
		Fax	(336) 725-6244		Central (West of I-95 and East of I-77):		Yes
		Website	www.evocorp.net		Mountains (West of I-77):		Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	Yes	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		7/29/2020		Area of state conducts work	
Excel Environmental Associates, PLLC 625 Huntsman Court Gastonia, NC 28054		Phone	(704) 853-0800		Coastal (East of I-95):		Yes
		Fax	(704) 853-3949		Central (West of I-95 and East of I-77):		Yes
		Website	www.excelengr.com		Mountains (West of I-77):		Yes
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted		8/4/2020		Area of state conducts work	
Fourstar Petroleum 1119 Beaumont Rd. Roanoke, VA 24019				Phone (540) 563-1022 Fax (540) 362-1802 Website www.fourstarpetro.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		Yes	
Containment Sump Testing:		No	Statistical Iventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		Yes	
Line Tightness Testing:		No				UST System Removal:		Yes	
Environmental Service Firms						Other:		Wayne Dispensers and Verifone POS	
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		No	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		No	Waste Disposal and Treatment:		No				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		No							

Company				Listing Submitted		11/14/2018		Area of state conducts work	
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111				Phone (303) 770-8884 Fax (303) 770-3636 Website www.GallowayUS.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Iventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		No	
Environmental Service Firms						Other:		UST System Design	
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		No	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		No	Waste Disposal and Treatment:		No				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		No							

Company		Listing Submitted		11/14/2018		Area of state conducts work	
Galloway 6162 South Willow Drive Suite 320 Greenwood Village, CO 80111		Phone (303) 770-8884 Fax (303) 770-3636 Website www.GallowayUS.com			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
Compliance Testing and Monitoring				UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms				Other:	UST System Design		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	11/9/2018	Area of state conducts work	
Geo-Hydro Engineers, Inc. 2748 Interstate Street Suite A Charlotte, NC 28208		Phone (704) 837-7174 Fax Website www.geohydro.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	11/14/2018	Area of state conducts work	
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28110		Phone (704) 845-4010 Fax (704) 845-4012 Website www.geologicalresourcesinc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		11/14/2018		Area of state conducts work	
Geological Resources, Inc. 3502 Hayes Road Monroe, NC 28110		Phone	(704) 845-4010		Coastal (East of I-95):		Yes
		Fax	(704) 845-4012		Central (West of I-95 and East of I-77):		Yes
		Website	www.geologicalresourcesinc.com		Mountains (West of I-77):		Yes
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	Yes		
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company			Listing Submitted		5/29/2018		Area of state conducts work	
Guardian Fueling Technologies 5116 Departure Drive Raleigh, NC 27616			Phone (919) 729-6980 Fax Website www.guardianfueltech.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring					UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes			
Containment Sump Testing:	Yes	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	Yes			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	Yes			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	Yes			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	Yes			
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes			
Leak Detection Monitoring Services:	Yes	Other: SafeGuard UST Inspection Services		UST Piping/Sump Installation:	Yes			
Line Tightness Testing:	No			UST System Removal:	Yes			
Environmental Service Firms					Other: FuelGuard Fuel Cleaning & Biocide Treatment			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No					
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No					
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No					
Oil and Solvent Recycling:	No	Other:						
Soil and Water Testing Lab:	No							

Company			Listing Submitted		11/14/2018		Area of state conducts work	
HARCO Services LLC PO Box 2347 Kennesaw, GA 30156			Phone (770) 917-8846 Fax (770) 917-0921 Website www.harcoservices.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring					UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No			
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	Yes			
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No			
Line Tightness Testing:	No			UST System Removal:	Yes			
Environmental Service Firms					Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No					
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No					
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No					
Oil and Solvent Recycling:	No	Other:						
Soil and Water Testing Lab:	No							

UST Service Provider List (Mountains)

Company				Listing Submitted		1/15/2019		Area of state conducts work	
Henry Nemargut Engineering Services 2211 Chestnut Street Wilmington, NC 28403				Phone (336) 316-0452 Fax (910) 762-3284 Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Inventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		No	
						Other:			
Environmental Service Firms									
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:		<u>Yes</u>	UST Equipment Verification:		<u>Yes</u>				
Environmental Engineer/Geologist Soil and GW Cleanu		<u>Yes</u>	Waste Disposal and Treatment:		No				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		No							

Company				Listing Submitted		11/14/2018		Area of state conducts work	
Highlands Environmental Solutions, Inc. 8410-D Falls of Neuse Road Raleigh, NC 27615				Phone (919) 848-3155 Fax (919) 848-4265 Website www.HESfast.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		<u>Yes</u>	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Inventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		<u>Yes</u>	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		<u>Yes</u>	
						Other:			
Environmental Service Firms									
Emergency Cleanup - Spill/Release:		<u>Yes</u>	UST Compliance Consultants:		<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:		<u>Yes</u>	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		<u>Yes</u>	Waste Disposal and Treatment:		<u>Yes</u>				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		No							

UST Service Provider List (Mountains)

Company				Listing Submitted	8/18/2020	Area of state conducts work	
INDUSTRY STANDARD CORRSION CONTROL - LLC		Phone	(252) 229-0485			Coastal (East of I-95): Yes	
400 HARBOR DRIVE		Fax	(704) 972-0300			Central (West of I-95 and East of I-77): Yes	
NEW BERN, NC 28560		Website	WWW.ISCC.TECH			Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipmment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	1/14/2020	Area of state conducts work	
INENCO, INC.		Phone	(704) 662-8192			Coastal (East of I-95): No	
132 W STATESVILLE AVE		Fax	(704) 662-8194			Central (West of I-95 and East of I-77): Yes	
MOORESVILLE, NC 28115		Website				Mountains (West of I-77): Yes	
Compliance Testing and Monitoring					UST Equipmment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Iventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	7/30/2020	Area of state conducts work	
JGD Associates, Inc. 92 Moore Road Avon Lake, Ohio 44012		Phone 4409336825 Fax Website www.jgdpe.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other: UST installation drawings	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	11/14/2018	Area of state conducts work	
Johnson, Spellman and Associates 350 Research Court Suite 130 Peachtree Corners, GA 30092		Phone (770) 447-4555 Fax Website www.jsace.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other: System design services - Engineering		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other: System design services - Engineering	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		5/27/2020		Area of state conducts work	
Labrador Environmental Consultants, P.C. (eastern 1450 Johnson Drive Williamston, NC 27892		Phone (252) 809-9130 Fax Website		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:	UST removal/closure				
Soil and Water Testing Lab:	No						

Company		Listing Submitted		8/18/2020		Area of state conducts work	
Law Petroleum, Inc. 11025 Arlington Church Road Charlotte, NC 28227		Phone	(704) 573-3535		Coastal (East of I-95):		Yes
		Fax	(704) 573-3535		Central (West of I-95 and East of I-77):		Yes
		Website			Mountains (West of I-77):		Yes
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	Yes			UST System Removal:		Yes	
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	11/19/2018	Area of state conducts work	
Martin & Slagle Geo Sciences, P.A. P.O. Box 1023 24 Lookout Terrace Black Mountain, NC 28711				Phone (828) 669-3929 Fax (828) 669-5289 Website martinandslagle.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	1/3/2020	Area of state conducts work	
MGF Environmental, PLLC 288 Gap Creek Rd. Fletcher, NC 28732				Phone (904) 814-3680 Fax Website http://www.mgfenvironmental.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		<u>Yes</u>	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		11/13/2018		Area of state conducts work	
Mineral Springs Environmental 4600 Mineral Springs Lane Raleigh, NC 27616		Phone (919) 266-8186 Fax Website				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		11/15/2018		Area of state conducts work	
National Tank Monitor, Inc. P.O. Box 987 Lonoke, AR 72086-		Phone (800) 643-8265 Fax (501) 764-4932 Website www.nationaltankmonitor.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	<u>Yes</u>	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	<u>Yes</u>	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	<u>Yes</u>	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		11/15/2018		Area of state conducts work		
NC PETROLEUM & CONVENIENCE MARKETERS 7300 GLENWOOD AVE. RALEIGH, NC 27612		Phone	(919) 782-4411				Coastal (East of I-95):	Yes
		Fax	(919) 872-4414				Central (West of I-95 and East of I-77):	Yes
		Website	WWW.NCPCM.ORG				Mountains (West of I-77):	Yes
Compliance Testing and Monitoring						UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No	
Leak Detection Monitoring Services:	No	Other:					UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	No	
Environmental Service Firms						Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes					
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No					
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No					
Oil and Solvent Recycling:	No	Other:			UST ENGINEERING			
Soil and Water Testing Lab:	No							

Company		Listing Submitted		7/30/2020		Area of state conducts work	
Nova Group GBC 442 South Main St Suite # 7 Davidson, NC 28036		Phone	(704) 258-5196			Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
		Fax					
		Website	https://www.novagroupgbc.com/				
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No		Dispenser Meter Repair/Calibration:	No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No		Leak Detection Equipment Installation Servicing:	No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No		Spill Bucket Installation Repair:	No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No		UST Equipment Installation - Other:	No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No		UST Equipment Repair:	No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		UST System Installation - Complete Systems:	No	
Leak Detection Monitoring Services:	No	Other:	Environmental compliance inspections		UST Piping/Sump Installation:	No	
Line Tightness Testing:	No				UST System Removal:	No	
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:	due diligence				
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted		7/30/2020		Area of state conducts work	
Peak Hydrogeologic, PLLC 470 Hogback Mountain Road Tryon, NC 28782				Phone (828) 817-5209 Fax Website www.peakhydrogeologic.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Inventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		No	
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		Yes	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		Yes	Waste Disposal and Treatment:		No				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		No							

Company				Listing Submitted		11/20/2018		Area of state conducts work	
Petroleum Equipment and Service, Inc. 4125 Sinclair Street PO Box 1949 Denver, NC 28037				Phone (704) 335-8801 Fax (704) 342-1672 Website www.petroleumequipment.net		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:		Yes	Overfill Prevention Equipment Operability Check:		Yes	Dispenser Meter Repair/Calibration:		Yes	
Containment Sump Testing:		Yes	Statistical Inventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		Yes	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		Yes	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:		Yes	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:		Yes	Other:			UST Piping/Sump Installation:		Yes	
Line Tightness Testing:		Yes				UST System Removal:		Yes	
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		No	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		No	Waste Disposal and Treatment:		No				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		No							

UST Service Provider List (Mountains)

Company				Listing Submitted		5/22/2019		Area of state conducts work	
Petroleum Tec 5420 Powerhouse Ct Concord, NC 28027				Phone (704) 804-1213 Fax Website www.petroileumtec.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:		No	Overfill Prevention Equipment Operability Check:		No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		No	Statistical Iventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		No	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		No	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		No	Other:		Tank Cleaning	UST Piping/Sump Installation:		No	
Line Tightness Testing:		No				UST System Removal:		No	
Environmental Service Firms						Other:		Tank Cleaning	
Emergency Cleanup - Spill/Release:		<u>Yes</u>	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		No	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		No	Waste Disposal and Treatment:		No				
Oil and Solvent Recycling:		No	Other:		Tank Cleaning				
Soil and Water Testing Lab:		No							

Company				Listing Submitted		3/19/2018		Area of state conducts work	
PetroTest Inc. 7 Dawn Rd. Benson, NC 27504				Phone (919) 902-3794 Fax Website www.petrotest.net		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring						UST Equipmment Service Contractors			
Automatic Line Leak Detector Testing:		<u>Yes</u>	Overfill Prevention Equipment Operability Check:		<u>Yes</u>	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:		<u>Yes</u>	Statistical Iventory Reconciliation Services:		No	Leak Detection Equipment Installation Servicing:		<u>Yes</u>	
Corrosion Protection Design Experts:		No	Spill Prevention Equipment Testing:		<u>Yes</u>	Spill Bucket Installation Repair:		<u>Yes</u>	
Corrosion Protection System Repairs:		No	Tank Tightness Testing:		<u>Yes</u>	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:		<u>Yes</u>	UST Internal Inspections (Integrity Assessments):		No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:		<u>Yes</u>	UST Internal Lining Inspections:		No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:		<u>Yes</u>	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:		<u>Yes</u>				UST System Removal:		No	
Environmental Service Firms						Other:			
Emergency Cleanup - Spill/Release:		No	UST Compliance Consultants:		No				
Environmental Engineer/Geologist - Site Checks:		No	UST Equipment Verification:		No				
Environmental Engineer/Geologist Soil and GW Cleanu		No	Waste Disposal and Treatment:		No				
Oil and Solvent Recycling:		No	Other:						
Soil and Water Testing Lab:		No							

UST Service Provider List (Mountains)

Company			Listing Submitted	11/14/2018	Area of state conducts work
PGP Services, LLC 1949 Candlewick Drive Fort Mill, SC 29715 Website			Phone (704) 619-1528 Fax (803) 802-2441		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	<u>Yes</u>	Overfill Prevention Equipment Operability Check:	<u>Yes</u>	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	<u>Yes</u>	Spill Prevention Equipment Testing:	<u>Yes</u>	Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No	UST Equipment Installation - Other:	<u>Yes</u>
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	<u>Yes</u>			UST System Removal:	<u>Yes</u>
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				
Company			Listing Submitted	7/30/2020	Area of state conducts work
Pilot Geological, PLLC 743 Park Lawn Court PO 128 Kernersville, NC 27285 Website www.pilotenviro.com			Phone (336) 310-4527 Fax (336) 310-4527		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes
Compliance Testing and Monitoring			UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	<u>Yes</u>
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>		
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	<u>Yes</u>		
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company		Listing Submitted	11/29/2018	Area of state conducts work	
Precision Tank Service P.O. Box 2040 20468 Chartwell Center Dr Cornelius, NC 28031		Phone (704) 892-8600 Fax (704) 892-8711 Website precisiontankservice.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:	Yes
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	Yes	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	Yes			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes		
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

Company		Listing Submitted	2/24/2020	Area of state conducts work	
Professional Service Industries, Inc. 5021 W W.T. Harris Blvd. Charlotte, NC 28269		Phone (704) 598-2234 Fax (704) 598-2236 Website http://www.intertek.com/building		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No
Line Tightness Testing:	No			UST System Removal:	No
				Other:	
Environmental Service Firms					
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No		
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No		
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No		
Oil and Solvent Recycling:	No	Other:			
Soil and Water Testing Lab:	No				

UST Service Provider List (Mountains)

Company				Listing Submitted	11/15/2018	Area of state conducts work	
Progress Environmental Group, Inc. 120 Fayette Street Winston-Salem, NC 27101				Phone (336) 722-9999 Fax (336) 722-9998 Website www.progressenvironmental.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No			Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No			Spill Bucket Installation Repair:	No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	<u>Yes</u>
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	<u>Yes</u>	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	11/15/2018	Area of state conducts work	
Protective Technologies, Inc. 711 Mill Street Camden, SC 29020				Phone (803) 424-0412 Fax (803) 424-0414 Website www.protectivetechnologiesinc.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	<u>Yes</u>			Dispenser Meter Repair/Calibration:	No
Containment Sump Testing:	<u>Yes</u>	Statistical Inventory Reconciliation Services:	No			Leak Detection Equipment Installation Servicing:	No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	<u>Yes</u>			Spill Bucket Installation Repair:	<u>Yes</u>
Corrosion Protection System Repairs:	<u>Yes</u>	Tank Tightness Testing:	No			UST Equipment Installation - Other:	No
Corrosion Protection System Testing:	<u>Yes</u>	UST Internal Inspections (Integrity Assessments):	No			UST Equipment Repair:	No
Leak Detection Equipment Operability Check:	<u>Yes</u>	UST Internal Lining Inspections:	No			UST System Installation - Complete Systems:	No
Leak Detection Monitoring Services:	No	Other:				UST Piping/Sump Installation:	No
Line Tightness Testing:	No					UST System Removal:	No
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	11/14/2018	Area of state conducts work	
Pyramid Environmental & Engineering PC 503 Industrial Ave Greensboro, NC 27406		Phone	(336) 335-3174		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
		Fax	(336) 691-0648				
		Website	www.pyramidenvironmental.com				
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	11/19/2018	Area of state conducts work	
Royster Oil Company, Inc. PO Box 1467 720 S Lafayette St Shelby, NC 28150		Phone	(704) 487-6344		Coastal (East of I-95): No Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes		
		Fax	(704) 487-7811				
		Website	www.roysteroil.com				
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	9/6/2018	Area of state conducts work	
SCS Engineers, PC 2520 Whitehall Park Drive, Suite 450 Charlotte, NC 28273				Phone (704) 504-3107 Fax Website www.scsengineers.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	12/12/2019	Area of state conducts work	
Shield Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208				Phone (704) 394-6913 Fax (704) 394-6968 Website www.shieldengineering.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	<u>Yes</u>						

Company		Listing Submitted		12/12/2019		Area of state conducts work	
Shield Engineering, Inc. 4301 Taggart Creek Road Charlotte, NC 28208		Phone (704) 394-6913 Fax (704) 394-6968 Website www.shieldengineering.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

UST Service Provider List (Mountains)

Company				Listing Submitted	11/14/2018	Area of state conducts work	
Simonsen Law Firm, P.C. 106 E. Queen St. P.O. Box 848 Edenton, NC 27932				Phone (252) 482-2175 Fax (252) 482-1355 Website www.simonsenlawfirm.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No			
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No			
Leak Detection Monitoring Services:	No	Other:	Legal Services related to all UST issues	UST Piping/Sump Installation: No			
Line Tightness Testing:	No			UST System Removal: No			
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	11/14/2018	Area of state conducts work	
Singleton Environmental, Inc. PO Box 2012 1301 Sand Hill Road Enka, NC 28728				Phone (828) 667-5001 Fax (828) 667-0105 Website www.singletonenvironmental.com		Coastal (East of I-95): No Central (West of I-95 and East of I-77): No Mountains (West of I-77): Yes	
Compliance Testing and Monitoring						UST Equipment Service Contractors	
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration: No			
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing: No			
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair: No			
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other: No			
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair: No			
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems: No			
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation: No			
Line Tightness Testing:	No			UST System Removal: <u>Yes</u>			
Environmental Service Firms						Other:	
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		11/16/2018		Area of state conducts work		
SR&R Environmental, Inc. 4920 Highway 421 N. PO Box 221 Wilmington, NC 28402		Phone	(910) 763-6274				Coastal (East of I-95):	Yes
		Fax	(910) 763-6132				Central (West of I-95 and East of I-77):	Yes
		Website	www.srrenviro.com				Mountains (West of I-77):	Yes
Compliance Testing and Monitoring						UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No		Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No		Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No		Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No		UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No		UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:	No				UST System Removal:		No	
Environmental Service Firms						Other:		
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No					
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No					
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	Yes					
Oil and Solvent Recycling:	Yes	Other:			Vacuum Truck Services			
Soil and Water Testing Lab:	No							

Company		Listing Submitted		11/14/2018		Area of state conducts work	
Superior Services PO Box 982 Hendersonville, NC 28793		Phone	(828) 698-6286		Coastal (East of I-95):		Yes
		Fax	(828) 698-6294		Central (West of I-95 and East of I-77):		Yes
		Website	www.superiorservices.us		Mountains (West of I-77):		Yes
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	Yes	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	Yes	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:	UST Repairs, AST inspection, testing, repair		UST Piping/Sump Installation:		No
Line Tightness Testing:	Yes			UST System Removal:		No	
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		11/14/2018		Area of state conducts work		
Terracon Consultants, Inc. 2701 Westport Road Charlotte, NC 28208		Phone	(704) 509-1777				Coastal (East of I-95):	Yes
		Fax	(704) 509-1888				Central (West of I-95 and East of I-77):	Yes
		Website	www.terracon.com				Mountains (West of I-77):	Yes
Compliance Testing and Monitoring					UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No		Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No		Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No		Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No		UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No		UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No		UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:			UST Piping/Sump Installation:		No	
Line Tightness Testing:	No				UST System Removal:		Yes	
Environmental Service Firms					Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	Yes					
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No					
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes					
Oil and Solvent Recycling:	No	Other:						
Soil and Water Testing Lab:	Yes							

Company		Listing Submitted		11/15/2018		Area of state conducts work	
Terraquest Environmental Consultants, P.C. 100 E. Ruffin Street Mebane, NC 27302		Phone	(919) 563-9091		Coastal (East of I-95):		Yes
		Fax	(919) 563-9095		Central (West of I-95 and East of I-77):		Yes
		Website	www.terraquestpc.com		Mountains (West of I-77):		Yes
Compliance Testing and Monitoring					UST Equipment Service Contractors		
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:	No		
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:	No		
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:	No		
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:	No		
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:	No		
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:	No		
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:	No		
Line Tightness Testing:	No			UST System Removal:	No		
Environmental Service Firms					Other:		
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	Yes				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	11/20/2018	Area of state conducts work	
TideLand Construction, LLC		Phone (252) 524-1644				Coastal (East of I-95): Yes	
3600 North Drive		Fax (252) 565-8724				Central (West of I-95 and East of I-77): Yes	
Greenville, NC 27834-		Website tidelandconstruction.com				Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:		Yes	
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		Yes	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:		Yes	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		Yes	
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		Yes	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	Yes				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company				Listing Submitted	8/12/2020	Area of state conducts work	
TIMMONS GROUP		Phone (919) 866-4951				Coastal (East of I-95): Yes	
5410 TRINITY ROAD, SUITE 102		Fax				Central (West of I-95 and East of I-77): Yes	
RALEIGH, NC 27606		Website http://www.timmons.com/				Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		No	
Environmental Service Firms				Other: SYSTEM DESIGN SERVICES - UST ENGINEERING			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	Yes				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other: SYSTEM DESIGN SERVICES - UST ENGINEERING					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		11/16/2018		Area of state conducts work	
UST Corrosion Management, Inc. 2764 Pleasant Rd. #10714 Fort Mill, SC 29708		Phone (888) 822-2431 Fax (803) 802-0561 Website www.ustcorrosion.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	Yes	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	Yes	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		7/9/2019		Area of state conducts work	
Valley Tank Testing 451 Apollo Beach Blvd. Apollo Beach, FL 33572		Phone (813) 671-9065 Fax (866) 328-9796 Website www.valleytank.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	Yes	Overfill Prevention Equipment Operability Check:	Yes	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	Yes	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	Yes	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	Yes	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	Yes	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	Yes	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	Yes	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	Yes			UST System Removal:			No
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company				Listing Submitted	5/22/2018	Area of state conducts work	
Vistabution LLC 8315 Six Forks Rd Suite 205 Raleigh, NC 27615		Phone (919) 844-9375 Fax (919) 861-0849 Website www.vistabution.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		No	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		No	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	Yes	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	Yes	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	Yes	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	Yes						

Company				Listing Submitted	9/6/2018	Area of state conducts work	
Vital Fuel Systems, Inc. 1076 Classic Road Apex, NC 27539		Phone (919) 303-7374 Fax (919) 303-7399 Website www.vitalfuelsystems.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other: ional, Upgrades. We do not work at retail fueling sites.			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

Company		Listing Submitted		9/6/2018		Area of state conducts work	
Vital Fuel Systems, Inc. 1076 Classic Road Apex, NC 27539		Phone (919) 303-7374 Fax (919) 303-7399 Website www.vitalfuelsystems.com		Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes			
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:		No	
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:		No	
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:		No	
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:		Yes	
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:		No	
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:		Yes	
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:		No	
Line Tightness Testing:	No			UST System Removal:		Yes	
Environmental Service Firms				Other: removal, Upgrades. We do not work at retail fueling sites.			
Emergency Cleanup - Spill/Release:	No	UST Compliance Consultants:	No				
Environmental Engineer/Geologist - Site Checks:	No	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanup	No	Waste Disposal and Treatment:	No				
Oil and Solvent Recycling:	No	Other:					
Soil and Water Testing Lab:	No						

UST Service Provider List (Mountains)

Company		Listing Submitted		8/13/2020		Area of state conducts work	
WithersRavenel, Inc. 115 MacKenan Drive Cary, NC 27511		Phone (919) 469-3340 Fax Website www.withersravenel.com				Coastal (East of I-95): Yes Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes	
Compliance Testing and Monitoring				UST Equipment Service Contractors			
Automatic Line Leak Detector Testing:	No	Overfill Prevention Equipment Operability Check:	No	Dispenser Meter Repair/Calibration:			No
Containment Sump Testing:	No	Statistical Inventory Reconciliation Services:	No	Leak Detection Equipment Installation Servicing:			No
Corrosion Protection Design Experts:	No	Spill Prevention Equipment Testing:	No	Spill Bucket Installation Repair:			No
Corrosion Protection System Repairs:	No	Tank Tightness Testing:	No	UST Equipment Installation - Other:			No
Corrosion Protection System Testing:	No	UST Internal Inspections (Integrity Assessments):	No	UST Equipment Repair:			No
Leak Detection Equipment Operability Check:	No	UST Internal Lining Inspections:	No	UST System Installation - Complete Systems:			No
Leak Detection Monitoring Services:	No	Other:		UST Piping/Sump Installation:			No
Line Tightness Testing:	No			UST System Removal:			<u>Yes</u>
Environmental Service Firms				Other:			
Emergency Cleanup - Spill/Release:	<u>Yes</u>	UST Compliance Consultants:	<u>Yes</u>				
Environmental Engineer/Geologist - Site Checks:	<u>Yes</u>	UST Equipment Verification:	No				
Environmental Engineer/Geologist Soil and GW Cleanu	<u>Yes</u>	Waste Disposal and Treatment:	<u>Yes</u>				
Oil and Solvent Recycling:	No	Other:	Phase I ESAs				
Soil and Water Testing Lab:	No						